

MV. BALMORAL: SURVEY AND REPAIR STRATEGY: 2005/6.

MONTH. 2005/6.	DEC.				JAN.				FEB.				MARCH.				APRIL.				MAY.				JUNE.											
WEEK COMMENCING.	5	12	19	26	2	9	16	23	30	6	13	20	27	6	13	20	27	3	10	17	24	1	8	15	22	29	6	12	19	26						
Prom deck steel renewal.	←																																			
Prom deck timber renewal.									←				→																							
Saloon bulkhead renewal.					←				→																											
Saloon – outfit, paint & finish.									←				→																							
Internal repairs.																	←				→															
Remove stbd belting.									←				→																							
Prepare belting timber.													←				→																			
Refit stbd belting.																					←				→											
Fit & weld window bars – stbd					←				→																											
Re-glaze – vandal damage.					←				→																											
Fit & weld window bars – port.													←				→																			
Statutory dry-dock survey.																	←				→															
Propeller repairs.																					←				→											
Load line survey.																					←				→											
Main engine repairs & insp'n.																					←				→											
Port genr. - top overhaul.																									←				→							
Stbd genr. – service.																									←				→							
Motor overhaul – altr & steerg.																									←				→							
Electrical repairs – general.	←				→				←				→				←				→				←				→							
Asbestos removal and sealing.									←				→																							
Sewage mods – if required.																					←				→											
Painting – hull.																									←				→							
- superstructure.																									←				→							
- deck details.																									←				→							
Stability book and assessments	←				→				←				→				←				→				←				→							
Commissioning & drills.																									←				→							
Vessel in service.																													←				→			

REPAIRS TO PORT SIDE OF QUARTERS
 REPAIRS TO STBD SIDE OF QUARTERS
 REPAIRS TO PORT SIDE OF QUARTERS
 REPAIRS TO STBD SIDE OF QUARTERS

CEED on 17/5

VESSEL IN SERVICE 16/6


 12/05